



# PAT Power Supply Brackets

PAT Power Supply Brackets are used to move your power supply (and other equipment) off your bench and onto your welder's vertical column. Why waste valuable bench space accommodating your welder's power supply?

The PAT Power Supply Brackets can be mounted either horizontally (left-hand or right-hand) or vertically.



PSB-1 Power Supply Bracket,  
Vertical Mount



PSB-3 Power Supply Brackets,  
"Universal" (left-hand or right-hand)  
Horizontal Mount

## Features:

- Aluminum construction provides a strong shelf area without excessive weight, which could upset the balance of the welder.
- The power supply nestles within the rim, so it cannot be accidentally pulled off and damaged.
- Power supply brackets are available for 3.5" and 4.0" support columns.
- Interface with the PAT slim line welder table to provide additional storage capacity in a small compact package.

*When other auxiliary devices are used, we recommend mounting a bracket on both sides of the ultrasonic welder. Placing the right bracket below the elevating knob provides an ideal location for a printer or other process monitoring equipment.*

## **PLASTIC ASSEMBLY TECHNOLOGIES, INC.**

8445 Castlewood Drive, Suite A, Indianapolis, IN 46250

T - (317) 841-1202 F - (317) 841-2717

[www.patsonics.com](http://www.patsonics.com)